

May 2021

Tel 604.792.1321 | Fax 604.792.9665 | <http://www.sd33.bc.ca/>



## Stitó:s Lá:lém totí:lt Update

- Weatherproofing and preliminary siding work, looking east at main entrance and office
- Looking west – 2-story is classrooms, 1-story is main entrance and office
- Window framing for entrance area / office



- Window and door framing facing river
- Inside classroom framing for windows and doors
- Inside classroom framing for sliding glass walls that connect classrooms to create flexible learning space



- Inside framing for project space between two classrooms (top right of photo)
- Openings in floor will be below skylights to allow daylight to the lower floor
- Looking down at entrance to east drop off and parking lot





- Learning Commons – starting work on sit/stand stairs
- Looking down from inside onto sit/stand stairs
- Looking in from outside onto sit/stand stairs



- Prep work for the seating area and exterior framing for Learning Commons
- Exterior framing looking from outside in





- Second floor decking is complete



- View of second floor decking from roof
- Roof membrane installation
- Roof for shop exterior storage area



- Exterior peel & stick weatherproof membrane and sunshade brackets
- Window framing and sunshade framing
- More sunshade framing

