

FOAMAWAY CARPET DEFOAMER

SECTION I

HARVARD CHEMICAL RESEARCH
3595 ZIP INDUSTRIAL BLVD.
ATLANTA, GA 30354

Date: 10/17/05

INQUIRY-

Phone: 404-761-0657

EMERGENCY- (800) 424-9300

HEALTH	1	0=Least
FLAMMABILITY		1=Slight
		2=Moderate
REACTIVITY	0	3=High
		4=Extreme

SECTION II HAZARDOUS INGREDIENTS/INFORMATION

HAZARDOUS COMPONENTS	CAS#	OSHA / PEL	ACGIH / TLV	OTHER / STEL	SK
NONE					

SECTION III -PHYSICAL/CHEMICAL CHARACTERISTICS

Boiling Point: 212 Degrees F
Vapor Pressure (mm Hg): ND
Vapor Density (Air=1): >1
Solubility in Water: COMPLETE

Appearance and odor: White liquid with bland odor.
Specific Gravity (H2O=1): 1.01
Melting Point: NA
Evaporation Rate:(Butyl Acetate=1) <1

SECTION IV-FIRE AND EXPLOSION HAZARD DATA

Flash Point (Method Used): NONE
Extinguishing Media: N/A.
Special Fire Fighting Procedures:

Flammable Limits: LEL: N/A UEL: N/A

Do not enter confined fire space without proper protective equipment including a NIOSH approved self-contained breathing apparatus.

Explosion Hazards: NONE

SECTION V-REACTIVITY DATA

Stability: Stable
Incompatibility (Materials to Avoid): Oxidizers or strong acids.
Hazardous Decomposition or Byproducts: Heat, carbon dioxide, and carbon monoxide.
Hazardous Polymerization: Will not occur.

SECTION VI-HEALTH HAZARD DATA

Health Hazards (Acute and Chronic): NONE KNOWN
Routes of Entry, Signs of Exposure, and Symptoms of Exposure:
SKIN and EYES: Severe irritant to eyes.
INHALATION: Irritation and difficulty in breathing
INGESTION: Gastric pain and vomiting.
Medical Conditions Generally Aggravated by Exposure: Unknown
Carcinogenic: NONE
Emergency and First Aid Procedures:

SKIN & EYE CONTACT: Rinse skin with clear water.
For eye contact immediately flush with clear running water for 15 minutes. Get medical attention.
INHALATION: Remove to fresh air. If breathing does not return to normal, get medical attention.
INGESTION: Immediately drink large quantities of water. Get medical attention.

SECTION VII-PRECAUTIONS FOR SAFE HANDLING AND USE

SPILLS: Dispose in accordance with federal and state regulations.
Handling and Storing: Keep container closed when not in use. Do not freeze. Follow label instructions.
Other Precautions: Keep this and all chemicals out of the reach of children.

SECTION VIII-CONTROL MEASURES

Respiratory Protection (Specify Type): For exposure above established limits (see section II) use NIOSH/MSMA approved dust/mist mask.
Ventilation: Mechanical: Not Recommended.
Protective Gloves: Rubber or neoprene.
Eye Protection: Safety Glasses .
Other Protective Clothing or Equipment: Eye wash station.

SECTION IX-ADDITIONAL INFORMATION

ENVIRONMENTAL BIODEGRADABILITY: BIODEGRADABLE.

SARA TITLE III REPORTING REQUIREMENTS
SECTION 302, 304 REPORTING NOT REQUIRED

311, 312

REPORTING REQUIRED FOR INVENTORY ABOVE TPQ.

313

REPORTING MAY BE REQUIRED FOR USERS IN MANUFACTURING SECTOR.

CERCLA

SAME AS SECTION 304